

09/423461




FIG.




FIG. 2

STEP

- 1 SET FIBERS
- 2 DEPRESS START SWITCH
- 3 ADVANCE FIBERS
- 4 CLEANING DISCHARGING
- 5 CHECK END FACE CONDITION
- 6 AUTOMATIC CENTERING
- 7 DISCHARGING FUSION
- 8 DISPLAY CONNECTION LOSS
- 9 SHIFT FIBERS
- 10 REINFORCING HEATING
- 11 END




FIG. 3

09/423461




FIG. 4




FIG. 5A




FIG. 5B




FIG. 5C




FIG. 6




FIG. 7




FIG. 8




FIG. 9

09/423461




FIG. 10




FIG. 11A




FIG. 11B




FIG. 12





FIG. 13

09/423461






FIG. 15

09/423461




FIG. 16

09/423461




FIG. 17




FIG. 18

09/423461




FIG. 19




FIG. 20




FIG. 21




FIG. 22

09/423461




FIG. 23

09/423461




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28

09/423461




FIG. 29




FIG. 30
PRIOR ART




FIG. 31A
PRIOR ART




FIG. 31B
PRIOR ART

09/423461

FIG. 32A
PRIOR ART




FIG. 32B
PRIOR ART

